Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2161Work Order Type: WeatherizationAudit Name: 14014SO2161

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2161 FAYETTEVILLE, TN 37334

Alt. Client ID: LINCOLN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client Name:
Client ID: 14014SO2161
Alt. Client ID: LINCOLN

Work Order (Bid Form)
Work Order Name: 14014SO2161

Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 4

	neral Air Sealing			Componen				
2. REP 3. REG 4. REP SEALIN		ORK AS I R LESS - REPLACI	NEEDE SEAL E INSU	ED WITH MAS LATION AF	TER DU			
5. W/S	AND INSTALL NEW STO	JRW HAR	DWAR	Estimated		≺	Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Miscellaneous Supplies	Infiltration Reduction	Each	1					
Labor	LABOR	Hour						
Other Detail								
] []		
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:				L				
Measure 2 Rep	place Heating [Electric]			Componen	nts			Inspected
Measure 2 Rep	-			Componen Estimated			Actual	Inspected
Measure 2 Rep Comment REPLA	-	Units		•		Qty		Inspecte
Measure 2 Rep Comment REPLA Material / Labor	CE UNIT			Estimated	1	Qty	Actual	
Measure 2 Rep Comment REPLA Material / Labor Heating Equipment	CE UNIT Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
Measure 2 Rep Comment REPLA Material / Labor Heating Equipment	Description / Comment Replacement hvac	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 2 Rep Comment REPLA Material / Labor Heating Equipment	Description / Comment Replacement hvac	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 2 Rep Comment REPLA Material / Labor Heating	Description / Comment Replacement hvac	Units Each Each	Qty 1 1	Estimated	1		Actual	

Client Name: Client ID: 14014SO2161 Alt. Client ID: LINCOLN

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: 14014SO2161 Version 8.5.0 Report Run On: 5/14/2010 Page 2 of 4

		LACEMENT DOOR			Componen	its			Inspected
C	comment REPLAC	CE BACK DOOR UNIT			Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Doors	REPLACEMENT DOOR	Each	1					
2	Labor	LABOR	Hour						
(Other Detail						1		
L									
L				M	Cub Total]	Sub Total:	
				weasur	e Sub Total:		,	Sub Total.	
	Measure 4 Fix I Comment	mproper Venting (Cloth	es Dryer)	Componen				Inspected
C	Comment		es Dryer		Estimated		Qty	Actual Unit Cost	Inspected
<i>C</i>		mproper Venting (Clother Description / Comment Metal Flex		Qty 1	-	1	Qty	Actual	
C # 1	Comment Material / Labor Health and Safety	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Items	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	Inspected Total
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Metal Flex	Units Each Hour	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Metal Flex	Units Each Hour	Qty 1 1	Estimated	1		Actual	

Report Run On: 5/14/2010

Comment	oke Detector is Needed			Componen	ts			Inspected
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	y Smoke / Carbon detector	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
	oor Barrier Needed sement/Crawlspace)			Componen	ts			Inspected
Comment								
				Estimated			Actual	
	Description / Comment Basement / crawlspace vapor barrier	<i>Units</i> Each	Qty 1	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
# Material / Labor						Qty		Total
# Material / Labor 1 Insulation	Basement / crawlspace vapor barrier	Each	1			Qty		Total
# Material / Labor 1 Insulation 2 Labor	Basement / crawlspace vapor barrier	Each	1			Qty		Total
# Material / Labor 1 Insulation 2 Labor	Basement / crawlspace vapor barrier	Each	1 1					Total
# Material / Labor 1 Insulation 2 Labor	Basement / crawlspace vapor barrier	Each	1 1	Unit Cost			Unit Cost	Total

Report Run On: 5/14/2010